



Airworthiness Directive

AD No.: 2012-0267R3

Issued: 09 November 2017

Note: This Airworthiness Directive (AD) is issued by EASA, acting in accordance with Regulation (EC) 216/2008 on behalf of the European Union, its Member States and of the European third countries that participate in the activities of EASA under Article 66 of that Regulation.

This AD is issued in accordance with Regulation (EU) 748/2012, Part 21.A.3B. In accordance with Regulation (EU) 1321/2014 Annex I, Part M.A.301, the continuing airworthiness of an aircraft shall be ensured by accomplishing any applicable ADs. Consequently, no person may operate an aircraft to which an AD applies, except in accordance with the requirements of that AD, unless otherwise specified by the Agency [Regulation (EU) 1321/2014 Annex I, Part M.A.303] or agreed with the Authority of the State of Registry [Regulation (EC) 216/2008, Article 14(4) exemption].

Design Approval Holder's Name:

Airbus

Type/Model designation(s):

A380 aeroplanes

Effective Date: Revision 3: 09 November 2017
 Revision 2: 25 July 2014
 Revision 1: 20 December 2013
 Original Issue: 03 January 2013

TCDS Number(s): EASA.A.110

Foreign AD: Not applicable

Revision: This AD revises EASA AD 2012-0267R2 dated 25 July 2014.

ATA 35 – Passenger Oxygen – Oxygen Distribution Pressure Line and Container Manifolds – Inspection

Manufacturer(s):

Airbus

Applicability:

Airbus A380-841, A380-842 and A380-861 aeroplanes, all manufacturer serial numbers, except aeroplanes that have embodied Airbus Modification (mod) 73623 in production.

Reason:

During maintenance checks of the passenger oxygen distribution line, some minor leaks were detected inside the oxygen containers. Investigations confirmed that a cracked manifold is the origin of the leak.

This condition, if not detected and corrected, could lead to a decrease of the available oxygen capacity, possibly resulting in exposure of the cabin occupants to hypoxia following a depressurization event.



Prompted by this potential unsafe condition, EASA issued AD 2012-0267 (later revised) to require repetitive special detailed inspections (SDI) of the oxygen Distribution Pressure Line (DPL) and container manifolds and, depending on the detected leak rate, accomplishment of applicable corrective action(s). That AD also required the reporting of the inspection results.

After EASA AD 2012-0267 was issued, Airbus developed mod 73623 for aeroplanes in production and issued Airbus Service Bulletin (SB) A380-35-8020 (retrofit mod 73624) for A380-842 and SB A380-35-8021 (retrofit mod 74766) for A380-841 and A380-861 aeroplanes, providing instructions for installing improved oxygen Passenger Dispensing Unit (PDU).

Consequently, EASA issued AD 2012-0267R1 and R2, respectively, to exclude from the Applicability aeroplanes that embody Airbus mod 73623 in production and to introduce the in-service installation of improved oxygen PDU as an optional terminating action for the repetitive SDI required by this AD.

Since AD 2012-0267R2 was issued, review of the requirement to report inspection results, detected during the repetitive SDI (including no findings) determined that reporting of no findings is not necessary any more. This AD is revised accordingly.

Required Action(s) and Compliance Time(s):

Required as indicated, unless accomplished previously:

Inspection(s):

- (1) Within 5 000 flight hours (FH) after aeroplane first flight, or within 1 000 FH after 03 January 2013 [the effective date of the original issue this AD], whichever occurs later, and, thereafter, at intervals not to exceed 5 000 FH, accomplish an SDI of the oxygen DPL and container manifolds in accordance with the instructions of Airbus SB A380-35-8019.

Corrective action(s):

- (2) If, during any SDI as required by paragraph (1) of this AD, the detected leak rate is not within the tolerance as defined in Airbus SB A380-35-8019 and/or damaged oxygen containers are found, accomplish the actions specified in paragraphs (3) and (4) of this AD.
- (3) Before next flight after detection of discrepancies as specified in paragraph (2) of this AD, accomplish a leak check of the oxygen DPL and record the elapsed time to pass from 5 bar to 2 bar in accordance with the instructions of Airbus SB A380-35-8019.
- (4) Within the applicable compliance time as defined in Paragraph 1.E.(2) of Airbus SB A380-35-8019, depending on the elapsed time, recorded as required by paragraph (3) of this AD, repair or replace the damaged oxygen container and accomplish a validation leak check of the oxygen DPL in accordance with the instructions of Airbus SB A380-35-8019.

Credit:

- (5) Accomplishment of a leak check (leak rate within the tolerance) on an aeroplane, before 03 January 2013 [the effective date of the original issue this AD], in accordance with the instructions of A380 Aircraft Maintenance Manual task 35-22-00-790-801, is acceptable to comply with the initial requirement of paragraph (1) of this AD for that aeroplane. After 03



January 2013 [the effective date of the original issue of this AD], repetitive inspections and corrective actions must be accomplished in accordance with the instructions of Airbus SB A380-35-8019.

Reporting:

- (6) From 03 January 2013 [the effective date of the original issue of this AD], within 30 days after each SDI, as required by paragraph (1) of this AD, report any discrepancy found to Airbus in accordance with the instructions of Airbus SB A380-35-8019.

Terminating action:

- (7) Repair or replacement of oxygen containers on an aeroplane, as required by paragraph (4) of this AD, does not constitute terminating action for the repetitive SDI as required by paragraph (1) of this AD for that aeroplane.
- (8) Modification of an aeroplane in accordance with the instructions of Airbus SB A380-35-8020 or Airbus SB A380-35-8021, as applicable to aeroplane model, constitutes terminating action for the repetitive SDI as required by paragraph (1) of this AD for that aeroplane.

Ref. Publications:

Airbus SB A380-35-8019, original issue dated 31 July 2012.

Airbus SB A380-35-8020, original issue dated 18 October 2013.

Airbus SB A380-35-8021, original issue dated 03 July 2014.

The use of later approved revisions of these documents is acceptable for compliance with the requirements of this AD.

Remarks:

1. If requested and appropriately substantiated, EASA can approve Alternative Methods of Compliance for this AD.
2. The original issue of this AD was posted on 05 November 2012 as PAD 12-135 for consultation until 03 December 2012. The Comment Response Document can be found in the [EASA Safety Publications Tool](#), in the compressed (zipped) file attached to the record for this AD.
3. Enquiries regarding this AD should be referred to the EASA Safety Information Section, Certification Directorate. E-mail: ADs@easa.europa.eu.
4. For any question concerning the technical content of the requirements in this AD, please contact: AIRBUS SAS - EIANA (Airworthiness Office), E-mail: account.airworth-A380@airbus.com.

